

August 1, 2019



Crenshaw/LAX Transit Project



Segment A



UG1- Cable barrier installation.



UG1- Cable safety barrier installation.



UG-1- 104th street south side no changes for UG1 Jet Fan conduit install.



UG-1- 104th street north side no changes for UG1 Jet Fan conduit install.



AVIATION/CENTURY- Reinstalling the galvanized fence anchor bolts at the Aviation Station



AVIATION/CENTURY- Grading for the Aviation Station plaza and parking lot.



AVIATION/CENTURY- Storm drain manhole prior to concrete placement at the yard.



AVIATION/CENTURY- Galvanized fence anchor bolt replacement at the Aviation Station.



AVIATION/CENTURY- Slurry backfill of the interceptor pit at the Aviation Station yard.



AVIATION/CENTURY- Stripping and setting forms for the galvanized bolt replacement.




AVIATION/CENTURY- Grading the plaza area at the Aviation Station.



AVIATION/CENTURY- Existing foundation to be removed at the NW corner of Aviation.



AVIATION/CENTURY- Grading for the plaza and parking lot at Aviation Station.



AVIATION/CENTURY- Slurry backfill of the interceptor pits at the Aviation Station yard.



AVIATION/CENTURY- Vacuum truck exposing a foundation to be removed at Aviation.



AVIATION/CENTURY- AVIATION/CENTURY- Vacuum.




MANCHESTER BRIDGE- SB track at Manchester Bridge DF replacement work.



MANCHESTER BRIDGE- NB track WSCC finisher hand grinding plinths for 0" plane.



MANCHESTER BRIDGE- WSCC concrete crew demoing out required plinths on SB track.



MANCHESTER BRIDGE- WSCC demoing out DF plinths that don't conform to Metro tollarances on Manchester Bridge SB track ..



FLORENCE/HINDRY - Sanding and prepping for paint at the Hindry Station.



FLORENCE/HINDRY - Paving on Florence at Hindry.



FLORENCE/HINDRY - Painting the TVM structure for the NB Hindry Station platform.



FLORENCE/HINDRY - Painting the ticket vending machine structure at the Hindry Station.

Segment B SEGMENT B2 STA 360+00 Crenshaw Blvd Park Mesa Heights – **At Grade Section** Slauson Ave Hyde Park Station Brea Ave SEGNEN BI SECULIAT BI P UG # 3 structure SEGMENT STA Fairview Heights Station **Downtown Inglewood** Station La Brea Bridge



FLORENCE/LA BREA - Setting the truncated dome handicap pavers at the La Brea Station.



FLORENCE/LA BREA - WSCC Remove metal guard rail wall at WB Florence and La Brea.



FLORENCE/LA BREA - Carrara Marble Place grout in yellow paver joints at La Brea Sta.



FLORENCE/LA BREA- WSCC Making grade and clear and grub for fence on north side of La Brea Sta.



HIGH STREET- Select Electric Stand TS and SL poles at High and Redondo.



HIGH STREET- WSCC Grading for cross gutter at High ST crossing.




UG3- Continued lighting installation at the southbound tunnel.



UG3- Continued installation of barrier wall along the track of the southbound portal.



UG3- Continued installation of OCR brackets along the southbound tunnel.



Segment C




UG4- LKC installation of cantilever arm brackets for OCR Expo Station UG-4.



UG4- LKC installation of cantilever arm brackets for OCR Expo Station UG-4.



UG4- HCC verifying track gauge on SB track UG4 MLK station.



UG4- HCC adjusting alignment on SB track UG4 using string line off Coast Survey scribes.



UG4- HCC on SB track in UG4 at MLK platform station.



CRENSHAW/VERNON- NETE electrical testing on MSWGR-S, contact resistance.



CRENSHAW/VERNON- NETE performing megger testing on MSWGR-N.




LEIMERT PARK STATION- Continued installation of elevator frame 3 & 4 at the platform level



LEIMERT PARK STATION- Prep connection points for entrance canopy and Elevator 1 & 2 steel at the topside.



LEIMERT PARK STATION- Painting on northbound OTE vent duct at the invert level.



MARTIN LUTHER KING JR. STATION- Painting on northbound OTE vent duct at the invert level.



MARTIN LUTHER KING JR. STATION- Installation of rebar for C Line encasement at the topside.




MARTIN LUTHER KING JR. STATION- Continued installation of water line vault at the topside.



EXPOSITION/CRENSHAW STATION – Aux Power north MCC1N emergency fan cable feeds.



EXPOSITION/CRENSHAW STATION – Painting on southbound OTE vent duct at the invert level.



EXPOSITION/CRENSHAW STATION – HCC adjusting alignment on NB track at Expo. station platform.