

**QUALITY ASSURANCE
BUS CLEANLINESS INSPECTION REPORT
July 2018**

	Div. 1	Div. 2	Div. 3	Div. 5	Div. 7	Div. 8	Div. 9	Div. 10	Div. 13	Div. 15	Div. 18
DASHBOARDS	9.6	9.5	9.8	7.7	8.6	9.3	9.4	9.1	9.2	8.4	8.3
DRIVERS AREA	8.6	7.7	8.3	7.6	8.4	8.0	8.8	8.9	8.4	8.7	7.9
TRANSOM/LEDGES	8.6	9.8	8.7	8.9	7.6	7.4	8.1	8.3	8.9	8.3	7.0
CEILING/VENTS	7.9	8.2	8.4	8.2	8.1	8.9	8.1	8.1	8.2	8.6	7.9
SEAT FRAMES	8.5	8.2	7.9	8.4	7.8	8.5	7.9	7.8	7.9	8.9	8.1
SEAT INSERTS	9.1	9.7	9.4	8.5	7.7	8.7	8.4	8.8	8.6	9.3	8.3
WINDOWS	7.8	8.3	8.0	7.5	8.2	8.2	8.3	8.1	7.8	8.4	7.4
SACRAFICIAL WINDOWS	9.3	9.7	8.9	8.7	8.8	9.0	9.6	9.4	9.2	9.1	8.5
DOORS	8.5	8.5	7.3	7.1	7.4	8.1	7.6	7.9	8.5	8.2	8.3
FLOORS	8.3	8.7	8.6	8.1	8.3	9.2	9.0	8.7	8.5	9.3	8.2
GUM	9.1	8.4	8.9	8.4	8.9	9.3	9.2	9.3	8.8	9.7	8.7
INT. GRAFFITI	9.5	9.8	9.4	9.3	9.8	9.6	9.6	9.1	9.6	9.8	9.5
WINDOW ETCHING	9.8	9.9	9.6	9.4	9.4	9.4	9.0	9.3	9.4	9.6	9.5
WATER SPOTTING	6.6	8.0	6.6	8.0	8.3	8.4	7.7	7.4	8.1	8.2	8.6
EXT. CLEANLINESS	8.3	7.5	9.5	9.1	9.0	6.8	8.9	9.3	8.4	9.5	9.0
EXT. GRAFFITI	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.9	10.0	10.0
WHEELS	8.1	5.5	6.8	9.0	6.8	6.7	7.6	8.4	7.4	7.9	7.0
EXT. BODY CONDITION	9.3	9.3	8.8	9.1	9.0	9.5	9.0	8.9	8.9	9.0	9.1
FRONT/REAR BUMPER CONDITION	9.3	8.8	8.6	9.4	8.9	9.3	8.7	8.9	8.2	8.4	8.6
July 2018 Overall Rating	8.7	8.7	8.6	8.5	8.5	8.7	8.7	8.7	8.6	8.9	8.4

