Presented by Vehicle Technology Department



Bus Procurement Status UpdateNABI 40 Foot CNG





40 Foot (75 Bus) Option Order

- All 75 buses have been delivered and accepted ahead of contract schedule.
- Seventy-Three buses have been released for service.
- Metro staff have begun the required closeout activities for this procurement.



Upgrades to the 40' Bus

- New style Operator Seat with extended seat belts.
- Remote Control outside mirrors with turn signals.
- Upgraded Front and Rear axles to accommodate heavier passenger loads.
- Padded Passenger Seats.



NABI 45 Foot New Style CNG High Capacity "Compo" Bus





45 Foot Composite Bus Order

- Ninety-One of the 100 buses have been delivered to date.
- Eighty- Six are in daily operation.
- Remaining Buses are scheduled for delivery 2 weeks ahead of final contract date, September 30, 2005.



45 Foot Composite Upgrades

- Four Wheel Disc Brakes.
- Remote and turn signal indicator mirrors.
- Padded passengers seats with "Rapid" approved fabric design.
- 15% more seat capacity.
- Wider exit doors.



NABI Advanced Design 60 foot CNG Articulated Bus





60 Foot Articulated BRT Vehicles

- Thirty-Three Articulated buses have been delivered to date. Six buses have been released to Division 8 where mechanic and operator training has begun.
- Thirty buses will be ready for the Orange Line opening in October.
- Three buses in the Rapid Bus scheme are currently going through make ready and release for revenue service.



Composite Bus Status Update

40 Foot Composite

45 Foot Composite







Composite Bus Status Update

Why a "Compo-bus?"

- Aerodynamic Design
- Composite vehicle design is lighter in weight.
- Better Fuel Economy.
- Reduced brake, engine & transmission wear.
- Resistant to corrosion.
- Projecting an extended vehicle life, 18 to 20 years.



Composite Bus Update

40 Foot Composite Buses

- Twenty buses have accumulated 1.3 million miles.
- Eight buses removed from service due to structural cracks in the front suspension area.
- NABI specialists are currently making repairs with updated technology used on the 45' composite bus.



Composite Bus Update

45 Foot Composite Buses

- 86 buses in service have accumulated 2.1 million miles.
- No structural issues similar to the 40 foot buses.
- No brake issues regarding the new Disc Brakes
- 65%-85% savings on accident repairs based on first Composite bus accident.

