



WESTSIDE SUBWAY EXTENSION PROJECT

Preliminary Geotechnical and Environmental Report

(Volume 2)



December 2011

THIS PAGE INTENTIONALLY LEFT BLANK

VOLUME 2

Summary

As part of PE phase, the following investigations were performed:

- Geotechnical
- Subsurface Gas
- Hydrogeologic
- Environmental Site Assessment
- Oil Well Survey
- Fault Investigation
- Noise and Vibration Studies

Volume 1 of the report provides the summaries of the field investigation programs for geotechnical, subsurface gas, hydrogeologic studies and oil well surveys; summary of laboratory testing program, description of project geology, evaluation of geologic seismic hazards, engineering properties of principal geologic units, results of ground motion study, geotechnical input for tunnel design and recommendations for stations. Only a summary of findings of fault investigation is included in Volume 1. The results of the comprehensive fault investigation are submitted in a separate report and not in this geotechnical and environmental report. Volume 1 includes Sections 1 through 14 along with an executive summary of the findings of PE phase.

Volume 2 (this volume) of the report presents the results of the field investigation: boring logs, monitoring well diagrams, Cone Penetration Test data, Dilatometer Test data, photographs of continuous core samples from sonic core borings and results of noise/vibration testing. Reports of oil well surveys, results of pump tests and boring logs of observation wells, National Pollution Discharge Elimination System (NPDES) permit are also included. Volume 2 consists of Appendices A through E and a breakdown of the appendices is presented in table of contents.

Volume 3 of the report presents the results of the laboratory testing for geotechnical, subsurface gas, hydrogeologic and environmental site assessment studies. Volume 3 consists of Appendices F through I and a breakdown of the appendices is presented in table of contents.

Table of Contents

VOLUME 2

Appendix A (Geotechnical Investigation)

Figure A-1.0: Unified Soil Classification System

Figures A-1.1a through A-1.19c: Logs of Rotary-Wash Borings (ACE Phase)

Figures A-1.20a through A-1.21k: Logs of Sonic Core Borings (ACE Phase)

Figures A-2.1a through A-2.80c: Logs of Rotary-Wash Borings (PE Phase)

Figures A-3.1a through A-3.17f: Logs of Sonic Core Borings (PE Phase)

Figures A-4.1 through A-4.101: CPT Logs (PE Phase)

Figures A-5.1 through A-5.3: DMT Plots (PE Phase)

Figure A-6: Crandall Sampler

Figures A-7.1 through A-7.6: Ground Water Monitoring Well Diagrams (ACE Phase)

Figures A-8.1 through A-8.11: Ground Water Monitoring Well Diagrams (PE Phase)

Figures A-9.1 through A-9.101: Sonic Core Photographic Logs (PE Phase)

Figures A-10.1 through 10.78: Noise/Vibration Testing (PE Phase)

Appendix B (Subsurface Gas Investigation)

Figures B-1.1a through B-1.20b: Logs of Hollow-Stem Auger Borings (ACE Phase)

Figures B-2.1a through B-2.19c: Logs of Hollow-Stem Auger Borings (PE Phase)

Figures B-3.0 through B-3.24: Gas Monitoring Well Diagrams (ACE Phase)

Figures B-4.1 through B-4.19: Gas Monitoring Well Diagrams (PE Phase)

Figures B-5.1 through B-5.8: Field Soil Gas and Hydrogen Sulfide Measurements

Appendix C (Hydrogeologic Investigation)

Figures C-1.1a through C-1.3d: Logs of Borings (PE Phase)

Figures C-2.1 through C-2.4: Ground-water Monitoring Well Diagrams

Figures C-3.1 through C-3.84: Notice of Intent (NOI)

Figures C-4.1 through C-4.2: National Pollution Discharge Elimination System (NPDES) Permit

Figures C-5.1 through C-5.18: California Regional Water Quality Control Board Permit

Appendix D (Environmental Site Assessment)

Figures D-1.1a through D-1.31b: Logs of Borings (PE Phase)

Appendix E (Oil Well Survey)

Figures E-1.1 through E-1.50: Oil Well Survey Reports