

[< HOME](#)

Metro Gold Line
Eastside Extension

UPDATE

Metro Gold Line Eastside
Extension

Photos by Ned Racine
4/15/2005

Photos, taken April 7, show workers boring holes in First Street, just west of Cummings Street, in preparation for chemical grouting. CalTrans required that grouting be injected under the U.S. 101 overpass to reduce any potential settling that might be caused by the tunnel boring machine working under First Street. When they are done, workers will have drilled approximately 250 holes under the overpass. Holes range from a depth of 47 to 52 feet.



4/7/2005



4/7/2005



4/7/2005



4/7/2005

