
January 1, 2019


Crenshaw/LAX Transit Project HANCOCK PARK KOREATOWN **LOS ANGELES CULVER CITY** LEIMERT PARK BALDWIN HILLS Leimert Park LADERA HEIGHTS INGLEWOOD WESTCHESTER MORNINGSIDE PARK LENNOX **HAWTHORNE** ATHENS El Segundo **EL SEGUNDO** GARDENA

Metro

- 8.5 miles Light Rail
- 8 Stations
- \$2,058.0 Million (Board approved revised LOP)

Segment A






GREENLINE UNDERPASS- BJ install, layout of restraining rail, and coring for skewed fasteners at Hinge 14.



GREENLINE UNDERPASS- BJ install, layout of restraining rail, and coring for skewed fasteners at Hinge 14.




GREENLINE UNDERPASS- Restraining rail placement and drill at SBW track.



MSE17- Top ballast rock cribbing.



UG1- Neal Electric installing tunnel lighting conduit near radio room.



UG1- Plastic based fixtures installed at 56+50.



UG1- Stripping barrier wall forms at UG-1



UG1- Placing concrete for the barrier wall at UG-1.



WESTCHESTER STATION- Neal E running CCTV conduit under NB Platform at.



WESTCHESTER STATION - RBT terminating Fire alarm Devices at Hindry Station.




AG) I 405 BRIDGE- Working on the concrete finish for the 405 Bridge.



(AG-7) FCBC PED UP- Applying primer to the SB side of the FCBC walkway underpass.

Segment B





B1 GUIDEWAY - Applying primer to the SB side of the FCBC walkway underpass



B1 GUIDEWAY - B1 Guideway east of West Sta backfill for pullbox relocation at T1-T2.



B1 GUIDEWAY - Setting forms for the Oak Street cross gutter.



B1 GUIDEWAY - Placing concrete for the Oak Street cross gutter.



B1 GUIDEWAY - Forming the drive approach on Oak.



B1 GUIDEWAY - VDL loops placed and AC being placed over them on Oak.



TPSS TPSS #1. NETE conducting pre-LFAT testing



TPSS- TPSS #1. WSCC Electrical continues to run traction 4-inch across Hornet Way.



TPSS- TPSS #1. Traction 4-inch conduits with kink in expansion couplings.



TPSS- TPSS #3. Pre-LFAT testing.




TPSS- TPSS #3. NETE was finishing AC switchgear function testing.



UG3 - Construction of the bulkhead wall at the south portal.



UG3 - Waterproofing above the roof underneath the deck panels at 67th street.





UG4 – Installation of electrical conduit at the southbound tunnel.



UG4 – Installation of electrical conduit at the northbound tunnel.



LEIMERT PARK STATION – Concrete placement for Stair #1 at the entrance structure.



LEIMERT PARK STATION – Construction of wall at North Emergency Exit #2.



LEIMERT PARK STATION – Preparation of the floor for sealant at the concourse level TC&C room .



LEIMERT PARK STATION – Metal ceiling hangers for the ceiling above the platform.



MARTIN LUTHER KING JR. STATION Installation of waterproofing for the west plaza wall.



MARTIN LUTHER KING JR. STATION- Concrete placement for wall EW-25.




MARTIN LUTHER KING JR. STATION- Removal of formwork from the interior elevator walls at the roof level.




MARTIN LUTHER KING JR. STATION- Placement of slurry backfill around Emergency Vent South.



EXPOSITION/CRENSHAW STATION – Installed of rebar and formwork for Emergency Exit Stairs #2 North.




EXPOSITION/CRENSHAW STATION – Removal of falsework at stairs 2 at the platform.



EXPOSITION/CRENSHAW STATION – Installation of electrical conduit at TPSS 10.



EXPOSITION/CRENSHAW STATION – Installation of formwork for safety walkway.



TUNNEL – Emergency lighting in the northbound tunnel between Expo and MLK Station.



TUNNEL – Southbound tunnel between EXPO and MLK Station.